





FIG. 2B















FIG.6





....



.












FIG. 12

22 9 38 FР 9B Ł 9A 2,2 9 P-Sub 9B FIG.13





64 kg FIG.16

ĩ٠,





FIG.17



13




FIG.18

FIG.19A

Peh MosTr

OUT

Noh DMosTr





FIG.20



Clamp Voltage vs Na Consentration





FIG.21

N-Clamp Voltage vs Na Consentration Stepped Junction N-Consentration $1 \times 10^{17} / \text{cm}^3$ \times j = 0. $2 \mu \text{m}$






Fig.22 Stepped Junction